

## 2003 ROVER 75 SEDAN

### Asset Details

<b>Build Date:</b>	9/2003
<b>Compliance:</b>	4/2004
<b>Make:</b>	ROVER
<b>Model:</b>	75
<b>Variant:</b>	
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	2.5 LITRE V6
<b>Transmission:</b>	4 SPEED AUTO
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	GOLD
<b>Int. Colour:</b>	FAWN
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	FRONT



### Asset Identification

<b>Odometer:</b>	101,794kms INDICATED	<b>Rego:</b>	XCS 155	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	SARRJZLLM4D308467	<b>PIN:</b>					
<b>Engine No:</b>	25K4FP56254608	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, LEATHER TRIM, POWER STEERING, POWER WINDOWS, SPARE WHEEL, SUNROOF, ELECTRIC SEATS, WOOD DASH & STEERING WHEEL, POWER MIRRORS, REAR PARKING SENSORS

### Tyres

<b>Front LHS:</b>	Good	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	--

### Condition

Location	Damage
FRONT LEFT BUMPER	SCRATCH
ROOF	DUCO DAMAGE