

## 1970 HILLMAN HUNTER ROYAL SEDAN

### Asset Details

|                      |                    |
|----------------------|--------------------|
| <b>Build Date:</b>   | 5/1970             |
| <b>Compliance:</b>   |                    |
| <b>Make:</b>         | HILLMAN            |
| <b>Model:</b>        | HUNTER             |
| <b>Variant:</b>      |                    |
| <b>Series:</b>       | ROYAL              |
| <b>Body Type:</b>    | SEDAN              |
| <b>Engine Size:</b>  | 1700 CC 4 CYLINDER |
| <b>Transmission:</b> | 3 SPEED AUTO       |
| <b>Fuel Type:</b>    | UNLEADED           |
| <b>Ext. Colour:</b>  | WHITE DUCO         |
| <b>Int. Colour:</b>  | GREEN              |
| <b>Doors:</b>        | 4                  |
| <b>Seats:</b>        | 5                  |
| <b>Drive Type:</b>   |                    |



### Asset Identification

|                   |                       |               |         |               |     |                       |     |
|-------------------|-----------------------|---------------|---------|---------------|-----|-----------------------|-----|
| <b>Odometer:</b>  | 2,224 MILES INDICATED | <b>Rego:</b>  | RKL 284 | <b>State:</b> | SA  | <b>Expiry:</b>        |     |
| <b>VIN:</b>       |                       | <b>PIN:</b>   |         |               |     |                       |     |
| <b>Engine No:</b> | HCM20348              | <b>Hours:</b> |         |               |     |                       |     |
| <b>Papers:</b>    | NO                    | <b>Keys:</b>  | 1       | <b>Books:</b> | YES | <b>Service Books:</b> | YES |

### Tyres

|                   |         |                   |         |                  |         |                  |         |               |         |
|-------------------|---------|-------------------|---------|------------------|---------|------------------|---------|---------------|---------|
| <b>Front LHS:</b> | Average | <b>Front RHS:</b> | Average | <b>Rear LHS:</b> | Average | <b>Rear RHS:</b> | Average | <b>Spare:</b> | Average |
|-------------------|---------|-------------------|---------|------------------|---------|------------------|---------|---------------|---------|

### Condition

| Location    | Damage                    |
|-------------|---------------------------|
| PAINTWORK   | SURFACE RUST & SOME CHIPS |
| REAR BUMPER | DENTED                    |