

## 05/2004 (CP) MERCEDES VITO EXTRA LONG 109 CDI VAN

### Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	5/2004
<b>Make:</b>	MERCEDES
<b>Model:</b>	VITO
<b>Variant:</b>	EXTRA LONG
<b>Series:</b>	109 CDI
<b>Body Type:</b>	VAN
<b>Engine Size:</b>	2 LITRE 4 CYLINDER
<b>Transmission:</b>	6 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	TURBO DIESE
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	5
<b>Seats:</b>	3
<b>Drive Type:</b>	REAR



### Asset Identification

<b>Odometer:</b>	215,580kms SHOWING	<b>Rego:</b>	XCN 269	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	WDF63960523051095			<b>PIN:</b>			
<b>Engine No:</b>	64698350048516			<b>Hours:</b>			
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

ABS, AIR BAG, AIR CON, CARGO BARRIER, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TOW BAR, TIE DOWN POINTS  
RUBBER LINED FLOOR IN REAR  
REVERSE CAMERA

KEY #30

### Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Average
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	---------

### Condition

Location	Damage
DUCO	DENTS & SCRATCHES
CENTRE BRAKE LENS	CRACKED
DRIVERS SEAT	TORN UPHOLSTERY
FUEL FLAP	TRIM MISSING

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.