

Wakefield Trucks



Wakefield Trucks

Wakefield Trucks Pty Ltd As Trustee for WAKEFIELD TRUCKS UNIT TRUST
A.B.N. 66 552 129 628

1174 - 1180 Port Wakefield Rd, Burton, SA 5110

P O Box 440, Salisbury, SA 5108

Ph: 08 8280 8133 Fax: 08 8280 6712

www.wakefieldtrucks.com.au

ARC Authority No. AU10557

Invoice # 576526		TAX INVOICE		*REPRINT* R/O # R75226		Page 1 of 3	
Doc. Date 16/06/2015	Customer Used Vehicles Reconditioning	Rego 5718	Stock No. 5718		Adviser JS		
Order No.	PO Box 440	Manufacturer WESTERN STAR TRUCK	Kms 993,926		Build Period 00/0000		
Customer Code USEREC	ABN	Vin 5KKXAF00XAPAP8987		Delivery Date 00/00/0000			
User Code LUCBRE	User Name and Address Brenton Luckraft	Engine No 79361926	Chassis No AP8987		Warranty Date 00/00/0000		
	PO Box 48	Model 4964FXC	Version SIG EGR		Body Type PM		
	ORROROO SA 5431	Next Service Date 00/00/0000	Date & Time In 27/04/2015 08:00		Body Color		
	Contact Brenton Luckraft	Next Service Kms 0	Date & Time Promised 27/04/2015 16:30		Hours Booked 100.00		
	Ph. (Home)						
	Ph. (Work) 8658 1419						
	Ph. (Other) 0428 581 419						

Product	Description	Quantity	Price Excl.
USED RECONDITIONING Claim # :			
LI	LABOUR INTERNAL 20- CARRIED OUT FULL VEHICLE INSPECTION. - NO REVERSE LIGHTS(RSF TAIL LIGHT ASSEMBLIES) - LHS BRAKE + CLEARANCE LIGHT INOP(RSF FAILED CLEARANCE LIGHT) - DRIVERS SEAT BELT NEEDS REPLACING(RSF SEAT BELT) - ELECTRIC HORN INOP(RSF FAILED HORN) - CHIP IN LHS WINDSCREEN - EXHAUST CLAMP RUBBING ON CAB MOUNT BRACKET(ADJUSTED EXHAUSTS) - A/C BELT CRACKING - FAN BELT HAS A FEW SMALL FRAYS FROM STONES - OIL LEAK AT FRONT OF HEAD, TIMING CASE AREA - LHS CAB MOUNT WORN(RSF CAB MOUNT, REPAIRED BROKEN CAB MOUNT BRACKET) - MOVEMENT IN BONNET PIVOTS - RADIATOR FINS BLOCKED(STEAM CLEANED) - RHF DRIVE AIR BAG CRACKING - RHR DRIVE BRAKE BOOSTER OVER STROKING - TRACK RODS ON DRIVE NEED BUSHES - BRAKE HOSE ON FRONT DRIVE RH NEED REPLACING(RSF HOSE) - O-RING ON DIFF COOLER MANIFOLD LEAKING - LHS REAR OF FUEL TAP LEAKING ON TAP(RSF FAILED TAP) - FLY WHEEL HOUSING LEAKING(RSF FAILD SEAL) - REAR ENGINE MOUNTS WORN(RSF MOUNTS) - STEER TYRES WEARING OUTER EDGES - TAIL LIGHTS HELD ON BY ZIP TIES - T/TABLE MOUNTING PLATE CRACKED AND HAS BEEN WELDED TO ANGLES EXCESSIVE MOVEMENT IN T/TABLE JAWS, NO ADJUSTMENT LEFT - TOP PLATE WEARING BOLT HEADS DOWN - LH INTAKE PIPES NEED REPLACING - RH+LH STEER BRAKE HOSE NEEDS REPLACING(RSF HOSES) - CLUTCH FORK GRINDING INTO PRESSURE PLATE(RSF CLUTCH AND MACHINED)	100	9,400.00

Continued ...

Wakefield Trucks



Wakefield Trucks

Wakefield Trucks Pty Ltd As Trustee for WAKEFIELD TRUCKS UNIT TRUST
A.B.N. 66 552 129 628

1174 - 1180 Port Wakefield Rd, Burton, SA 5110

P O Box 440, Salisbury, SA 5108

Ph: 08 8280 8133 Fax: 08 8280 6712

www.wakefieldtrucks.com.au

ARC Authority No. AU10557

Invoice # **576526**

TAX INVOICE

REPRINT

R/O # **R75226**

Page 2 of 3

FLY WHEEL, RSF INPUT SHAFT, RSF REAR MAIN SEAL)
- DRAG LINK HAS EXCESSIVE MOVEMENT(RSF DRAG LINK)
- LH KING PIN ON LIMIT FOR MOVEMENT
- P-CLAMPS ON TRANS COOLER LINES FAILED(RSF CLAMPS)
- FRONT DRIVE PRIMAX BUSHES HAVE MOVEMENT
- RHR SLACK ADJUSTER FAILED(RSF ADJUSTER)
- DOWNLOADED FAULT CODES, RECONNECTED CRANK SENSOR PLUG, R&R RHR TYRE
AND SET ABS SENSOR GAP. ALL OK.

SUB	CHECK FAULT CODES	1	99.18
SUB	MACHINE CUMMINS FLYWHEEL	1	114.00
SUB	FACE FLYWHEEL HOUSING ONLY	1	308.00
1221022034	HOSE #8-C/B-06MPTXSAE 45 SWVL	2	73.44
L24VT8334A11	LINK-DRAG STD AXLE AUST	1	461.60
94816HNAR	MDL 48 LED REVERSE HZL & R/GKT	2	220.00
631013404S	HORN-ELECTRIC 12V	1	26.16
522033434	BELT-SEAT 3 POINT	1	319.50
1221021055	HOSE 8 C/B (2) SAE 45 SWVL END	1	39.32
54X8	ELBOW-45-MALE-SAE-45 FLARE/NPT	1	3.72
14CX1	1/4 X 1 UNC GR5 ZP BOLT	4	0.80
14WH	1/4 ZP GR8 HARDENED WASHER	8	0.48
14CNN	1/4 UNC ZP NYLOC NUT	4	0.28
4965569	KIT SEAL	1	212.17
208938583	CLUTCH KIT-14SPL 2.00 EP ADVAN	1	1,414.74
K3768	CLUTCH INSTALLATION KIT	1	265.00
120043402	MOUNT-ENGINE UPPER 55 DURO	2	95.98
120043401	MOUNT-LOWER ENGINE DURO 55	4	90.68
3678740	F/WHEEL BOLT(SIGNATURE)	12	222.60
106C1498	SHAFT-CLUTCH	1	18.01
252103407	SHAFT-CLUTCH RELEASE RH	1	71.75
13835	O RING	2	1.60
13653	O-RING	2	4.18
13834	O-RING	1	0.34
5568544	O RING	1	0.68
4965688	GASKET FLYWHEEL HOUSING	1	179.07
3026134	GASKET	1	15.17
CLT008P	TUBE-LUBE T/O BEARING	1	10.58
85003	ELBOW 5/32IN PUSH X 1/8IN NPT	1	6.73
38FX214	3/8 X 2 1/4 UNF GR5 ZP BOLT	1	0.71
38WH	3/8 ZP GR8 HARDENED WASHER	2	0.16
38FNN	3/8 UNF ZP NYLOC NUT	1	0.17
4305294	GASKET-SHIFT C	1	4.31
5007417	BOLT-SPL H/R RETAINER 12MM	4	4.28
34FX5	3/4 X 5 UNF GR8 ZP BOLT	1	3.59
34FNC	3/4 UNF CONELOCK NUT	1	1.25
34WH	3/4 ZP GR8 HARDENED WASHER	2	0.82
5007417	BOLT-SPL H/R RETAINER 12MM	4	4.28

Continued ...

Wakefield Trucks



Wakefield Trucks

Wakefield Trucks Pty Ltd As Trustee for WAKEFIELD TRUCKS UNIT TRUST
A.B.N. 66 552 129 628

1174 - 1180 Port Wakefield Rd, Burton, SA 5110

P O Box 440, Salisbury, SA 5108

Ph: 08 8280 8133 Fax: 08 8280 6712

www.wakefieldtrucks.com.au

ARC Authority No. AU10557

Invoice #	576526	TAX INVOICE	*REPRINT*	R/O #	R75226	Page 3 of 3
A1866875001	ISOLATOR-CAB SUPPORT-FRT-SOFT	1	57.31			
V590P8	VALVE BALL	1	34.26			
12498	GLOBE BAYONET 12V 21W BA15S	1	0.66			
34FX212	3/4 X 2 1/2 UNF GR8 ZP BOLT	8	17.60			
34FNC	3/4 UNF CONELOCK NUT	8	10.00			
34WH	3/4 ZP GR8 HARDENED WASHER	16	6.56			
540203419MDC	BUTTON-SNAP-HAMPTON-PANEL-TAN	8	47.20			
223465V	PRESSURE PROT VALVE	2	53.92			
1868X6X6	CONNECTOR-Q/C A/B J844 MALE	2	5.32			
1869X6X6	ELBOW-Q/C A/B J844 MALE 90 DEG	1	4.60			
1868X4	CONNECTOR-Q/C A/B J844 MALE	1	2.26			
1869X4X4	ELBOW-Q/C A/B J844 MALE 90 DEG	1	3.97			
1869X4S	ELBOW MALE SWIVEL 1/4 X 1/8	1	5.66			
1869X4S	ELBOW MALE SWIVEL 1/4 X 1/8	1	5.66			
BW236577	GASKET,GOVERNOR	1	1.43			
			Sub Total:		13,951.74	

Banking Details:

Wakefield Trucks Pty Ltd
Commonwealth Bank - Salisbury
BSB: 065-122
Acc No: 0033 2073

Parts:	4,030.56
Labour:	9,400.00
Others:	521.18
Sub Total:	13,951.74
Total GST:	0.00
Rounding:	0.00
Total:	13,951.74