

Minor Service Major Service Inspection Other Maintenance

A

B

C

D

PM 61

| DATE     | NAME   | DESCRIPTION                                | HOURS | KM'S      |
|----------|--------|--------------------------------------------|-------|-----------|
|          |        | NEW MOTOR                                  |       |           |
| 13/11/13 | R Hill | MINOR SERVICE (1038411)                    | 1 1/2 | 864,002 ✓ |
| 14/12/13 | R Hill | MAJOR SERVICE (1038412)                    | 2     | 881,424 ✓ |
| 4/12/13  | R Hill | MINOR SERVICE (1038456)                    | 2     | 875,827 ✓ |
| 8/2/14   | Blue   | Minor service (1038457)                    | 1     | 896,445 ✓ |
| 20/2/14  | Blue   | <del>Inspection</del> Inspection (1038529) | 2     | ✓         |
|          |        | Fitted new Rear shockers Fitted            |       |           |
|          |        | bushes to LHF drive. Removed               |       |           |
|          |        | steering wheel                             |       |           |
| 20/2/14  | R Hill | Remove RHF drive wheel, to                 | 8     |           |
|          |        | replace wheel seat, clean shoes            |       |           |
|          |        | and bearings, Put wheel                    |       |           |
|          |        | back on, Put axle in.                      |       |           |
| 2        |        | check wiring for horn, replace             |       | ✓         |
|          |        | horn (1038530)                             |       |           |
| 27/2/14  | R Hill | Go to RTA and put truck                    | 1 1/2 | ✓         |
|          |        | over pits (1038531)                        |       |           |
| 27/2/14  | R Hill | MAJOR SERVICE (1038533)                    | 2     | 902,149 ✓ |
| 18/3/14  | R Hill | MINOR SERVICE (1038571)                    | 2     | 910,553 ✓ |
| 5/4/14   | R Hill | MAJOR SERVICE (1038622)                    | 2     | 920,772 ✓ |
| 30/4/14  | R Hill | MINOR SERVICE (1038717)                    | 2     | 934,093 ✓ |
| 16/5/14  | R Hill | MAJOR SERVICE (1038718)                    | 2     | 941,680 ✓ |
| 20/6/14  | R Hill | MINOR SERVICE (1038719)                    | 2     | 951,372 ✓ |
| 3/8/14   | R Hill | change alternator, change batteries        | 4     | ✓         |
|          |        | change seat in truck (1038830)             |       |           |
| 29/9/14  | R Hill | MAJOR SERVICE (1038831)                    | 2     | 962,198 ✓ |

Minor  
ServiceMajor  
Service

Inspection

Any other  
Maintenance

|              |        |                                                                                              | PM 61 |           |
|--------------|--------|----------------------------------------------------------------------------------------------|-------|-----------|
| DATE         | NAME   | DESCRIPTION                                                                                  | HOURS | KM'S      |
| 6/12/12      | P Hill | MINOR SERVICE (1037987)                                                                      | 2     | ✓ 711,478 |
| 19/1/13      | P Hill | MAJOR SERVICE (1038025)                                                                      | 2     | ✓ 733,828 |
| 24/1/13      | P Hill | MINOR SERVICE                                                                                | 2     | ✓ 741,934 |
| 31/1/13      | P Hill | weld tank strap and go to<br>tapeceema mill and change                                       | 2     |           |
| * 7/1/12     | P Hill | C-INSPECTION                                                                                 | 4     | ✓ 711,047 |
| 5/2/13       | P Hill | MAJOR SERVICE                                                                                | 2     | ✓ 751,512 |
| 14th 18/2/13 | P Hill | MAJOR SERVICE                                                                                | 2     | ✓ 761,082 |
| ✓ 16/3/13    | Blue   | MAJOR SERVICE (1038100)                                                                      | 2     | 781,841   |
| ✓ 18/3/13    | P Hill | change coolant sensor (1038101)                                                              | 1     |           |
| ✓ 21/3/13    | P Hill | change 2-Beam Lighter (1038102)                                                              | 3     |           |
| ✓ 15/4/13    | P Hill | MINOR SERVICE (1038102)                                                                      | 2     | 789,767   |
| ✓ 13/5/13    | P Hill | MAJOR SERVICE (1038174)                                                                      | 2     | 802,253   |
| ✓ 7/6/13     | P Hill | MINOR SERVICE (1038175)                                                                      | 1 1/2 | 811,731   |
| ✓ 29/6/13    | P Hill | MAJOR SERVICE (1038176)                                                                      | 2     | 829,491   |
| ✓ 19/8/13    | P Hill | MINOR SERVICE (1038220)                                                                      | 2     | 838,694   |
| ✓ 20/8/13    | P Hill | fit new stereo to truck (1038260)                                                            | 2     | -         |
| ✓ 19/8/13    | Blue   | Tightened up gearbox crossmember (1038262)                                                   | 3     |           |
|              |        | checked over clutch air                                                                      |       |           |
|              |        | cylinders & Blkr of Rear cylinder.                                                           |       |           |
|              |        | tightened guard plate.                                                                       |       |           |
| ✓ 28/8/13    | P Hill | Drain Hydraulic oil and remove<br>pump, fit new pump and fill with<br>oil and test (1038294) | 3     |           |
| ✓ 29/8/13    | P Hill | Drain and replace diffials (1038295)                                                         | 1     | 838,694   |
| ✓ 9/10/13    | P Hill | MINOR SERVICE (1038410)                                                                      | 1 1/2 | 853,951   |

PM 61

| DATE    | NAME   | DESCRIPTION                                                                                  | HOURS | KM'S      |
|---------|--------|----------------------------------------------------------------------------------------------|-------|-----------|
| 29/3/12 | Mg.H   | Fix Back Right light                                                                         | 1     | ✓ 1036572 |
| 26/3/12 | R.Hill | MINOR SERVICE (1036573)                                                                      | 2½    | ✓ 1036623 |
| 29/4/12 | Blue   | Travel to truck fit water tank                                                               | 1     | ✓ 1036689 |
| 21/4/12 | Blue   | Remove heater tap & plug<br>of hole fill with water                                          | 2     | ✓ 1036690 |
| 7/5/12  | R.Hill | MAJOR SERVICE (1036809)                                                                      | 2     | ✓ 1036808 |
| 7/5/12  | Blue   | Help with service                                                                            | 1     | ✓ 1036810 |
| 17-5-12 | David  | ASSIST BLUE WITH GEARBOX ASSY                                                                | ½     | ✓ 1036876 |
| 15/5/12 | Blue   | Remove gearbox clutch flywheel                                                               | 7     | ✓ 1036877 |
| 16/5/12 | Blue   | Fit flywheel & new clutch fitted<br>new crossshaft bushes new input<br>shaft & bearing cover | 7     | ✓ 1036878 |
| 17/5/12 | Blue   | Refitted gearbox & assembled<br>truck                                                        | 7     | ✓ 1036879 |
| 18/5/12 | Blue   | Finish assembling truck &<br>Remove fuel tank                                                | 6     | ✓ 1036880 |
| 28-5-12 | David  | ASSIST DEMO BREAKDOWN                                                                        | 1½    | ✓ 1036956 |
| 29/5/12 | R.Hill | replace air line to height<br>valve                                                          | 1     | ✓ 1036980 |
| 28-5-12 |        | NEW AIR "COMP" FITTED BY<br>Cummins. (WARRANTY)                                              | 695   | ✓ 1036980 |
| 14-6-12 | David  | Replace broken FAN CLUTCH                                                                    | 6½    | ✓ 1037122 |
| 14/6/12 | Mg.H   | assist R.Hill with GEAR SERVICE                                                              | 1     | ✓ 1037174 |
| 14/6/12 | R.Hill | MINOR SERVICE                                                                                | 2     | ✓ 1037123 |
| 27/6/12 | R.Hill | travel to Nelson and fix<br>radiator hose, fill with coolant                                 | 2½    | ✓ 1037223 |
| 7/11/12 | R.Hill | MAJOR SERVICE (1037986)                                                                      | 2     | ✓ 1037947 |

|          |        |                                                                                         | PM    | 61              |
|----------|--------|-----------------------------------------------------------------------------------------|-------|-----------------|
| DATE     | NAME   | DESCRIPTION                                                                             | HOURS | KM'S            |
| 29/8/11  | Jared  | Minor service ✓ 1035179                                                                 | 1.5   | 621107          |
| 2/9/11   | Jared  | Replace indicator globe, reset relay.                                                   | 1/2   |                 |
|          |        |                                                                                         | ✓     | 1035227         |
| 5/9/11   | Jared  | Major service, Replace RH side rear clearance light, & R Right tail light assembly.     | 1.5   | 634,941         |
|          |        |                                                                                         | ✓     | 1035344         |
| 16/9/11  | P.Hill | assist with service                                                                     | 2     | ✓ 1035345       |
| 29/9/11  | P.Hill | MINOR SERVICE ✓                                                                         | 2     | 643,599 1035448 |
| 18/10/11 | P.Hill | MAJOR SERVICE                                                                           | 2 1/2 | 651,936         |
|          |        | weld exhaust bracket ✓                                                                  |       | 1035519         |
| 9-11-11  | David  | Banner repair                                                                           | 1     | ✓ 1035707       |
| 15-11-11 | David  | Re connect Banner & Load                                                                | 1/2   | ✓ 1035757       |
| 2-2-12   | David  | INSTALL NEW AIR CYLINDERS ON CLUTCH, FIT NEW BUMP STOP TO CAB, CHECK INWARD RUD FOR CAB | 5 1/2 | ✓ 1036178       |
| 14-2-12  | David  | FIT STARTER MOTOR                                                                       | 2     | ✓ 1036236       |
| 15/2/12  | P.Hill | Reline Right side drive brakes                                                          | 6     | ✓ 1036271       |
| 16-2-12  |        | MINOR SERVICE                                                                           |       | 659,413         |
| 16/2/12  | P.Hill | Reline Left hand rear brake                                                             | 2     | ✓ 1036272       |
| 21/2/12  | P.Hill | remove Park brake valve                                                                 | 2     | ✓ 1036287       |
| 25-2-12  | David  | HEADLIGHT REPAIR R/H                                                                    | 1     | ✓ 1036314       |
| 13/3/12  | Math   | full <sup>HELP WITH</sup> Service                                                       | 2     | ✓ 1036426       |
| 13/3/12  | P.Hill | MAJOR SERVICE (1036427)                                                                 | 2     | ✓ 674,101       |
| 14-3-12  | David  | CLEAN AIR FILTER (AC)                                                                   | 2     | ✓ 1036445       |
| 24-3-12  | David  | MAKE UP AIR CON FITTINGS                                                                | 1 1/2 | ✓ 1036515       |

PM61

| DATE               | NAME             | DESCRIPTION                                                               | HOURS   | KMs     |
|--------------------|------------------|---------------------------------------------------------------------------|---------|---------|
| 7.4.11             | Jared            | Tighten front u-bolts ✓                                                   | 7       | 1033824 |
|                    |                  | Repair clutch cylinder mount                                              |         |         |
| 7-4-11             | PIAN             | "C" INSPECT ✓ 1033833                                                     | 3 1/2 ✓ | 562531  |
| 11-4-11            | Cummins          | TURBO • Fuel Pump • COMPRESSOR<br>AND TUNE UP.                            |         |         |
| <del>20-4-11</del> | <del>Jared</del> |                                                                           |         |         |
| 12-4-11            | DAVID            | REPLACED EXHAUST FLANGE ✓                                                 | 1 1/2 ✓ | 1033888 |
| 6/5/11             | Jared            | Major Service (1034055) ✓                                                 | 2       | 570037  |
| 11/5/11            | Blue             | Removed gearbox & Remove<br>broken bolts ✓                                | 5       | 1034263 |
| 20/5/11            | Blue             | Refitted gearbox ✓                                                        | 7       | 1034264 |
| 31/5/11            | Jared            | Minor service, replace LHF<br>booster. ✓                                  | 3       | 579493  |
| 8/6/11             | Jared            | Repair pto air line ✓                                                     | 1       | 1034412 |
| 9/6/11             | Jared            | Replace end cap on pto spool. ✓                                           | 3       |         |
| 15/6/11            |                  | top up gearbox ⑥ ✓                                                        |         | 1034474 |
| 22/6/11            | Jared            | Remove a rear section of gearbox                                          | 8.5 ✓   | 1034532 |
| 16/6/11            | Jared            | Strip rear section of gearbox, clean<br>up parts ✓                        | 6       | 1034535 |
| 17/6/11            | Jared            | Rebuild rear section of gearbox ✓                                         | 6 ✓     | 1034534 |
| 24/6/11            | Jared            | Rebuild rear section of gearbox<br>put back in truck ✓                    | 7       | 1034535 |
| 22/6/11            | Jared            | Fill air tanks to repair exhaust,<br>road test. ✓                         | 7       | 1034536 |
| 23/6/11            | Jared            | Wash gearbox & motor, check batteries<br>refit checker plate & hook up ✓  | 6       | 1034537 |
| 25/6/11            | P.ULL            | MAJOR SERVICE 1034574 ✓                                                   | 2 1/2   | 589,729 |
| 27/7/11            | Jared            | Replace LH Indicator in bullbar,<br>tape up LH front guard ✓              | 1       | 1034858 |
| 28/7/11            | P.ULL            | MINOR SERVICE 1034842 ✓                                                   | 2       | 602,017 |
| 30-7-11            | David            | FIT EXTENSION TO EXHIST STAY ✓                                            | 3 1/2   | 1034866 |
| 4/8/11             | Jared            | Replace loop kit on LHS, repair<br>mudguard & flap, test air compressor ✓ | 2 1/2   | 1034896 |
| 11/8/11            | Jared            | Tighten RH front mudguard pole,<br>Replace LH H/Light globe. ✓            | 1/2     | 1034972 |
| 15/8/11            | P.ULL            | MAJOR SERVICE ✓                                                           | 2 1/2   | 611,677 |
| 27/8/11            | Blue             | Solder up wire of low water<br>sender ✓                                   | 1       | 1035024 |
|                    |                  |                                                                           |         | 1035184 |

PM61

| DATE     | NAME  | DESCRIPTION                                                                                          | HOURS | KMs     |
|----------|-------|------------------------------------------------------------------------------------------------------|-------|---------|
| 20.8.10  | pete  | fix air leak under cab ✓                                                                             | 2     | 1032651 |
| 15.9.10  | pete  | minor Service (440659) ✓                                                                             | 1 1/2 | 1032652 |
| 6.10.10  | pete  | major Service (457706) ✓                                                                             | 2     | 1032705 |
| 14.10.10 | Jared | minor Service (401000) ✓                                                                             | 1     | 1032726 |
| 20.10.10 | pete  | fix headlights/spotlights.<br>take uni out and tighten<br>gearbox yoke ✓                             | 3     | 1032798 |
| 23.10    | pete  | change shocker on<br>RHF of Drive/help with<br>service pull tailshaft<br>out, tighten gearbox yoke ✓ | 2     | 1032799 |
| 23.10    | Jared | major Service (471408) ✓                                                                             | 2     | 1032800 |
| 28.10    | Jared | replace height valve.<br>tighten gearbox yoke/hook<br>up to spare trailer ✓                          | 3 1/2 | 1032815 |
| 3.11.10  | Jared | replace clutch brake ✓                                                                               | 1     | 1032898 |
| 4.11.10  | Jared | replace clutch brake ✓                                                                               | 1     | 1032899 |
| 23.11.10 | Jared | replace 2 beam<br>major Service (489351) ✓                                                           | 5     | 1032967 |
| 9.11.10  | pete  | minor Service. ✓                                                                                     | 1     | 1033103 |
| 10.12.10 | Jared | minor Service<br>tighten Ubolts                                                                      | 2 1/2 | 1033104 |
| 11.12.10 | Jared | fix water leak in cab ✓                                                                              | 1     | 1033105 |
| 15/2/11  | Jared | Major service ✓                                                                                      | 4     | 1033424 |
| 15.12.10 | Jared | adjust clutch<br>adjust free travel/clean clutch brake                                               | 2     | 1033152 |
| 16.12.10 | rick  | removed sheppard<br>shockers and replaced with new ones                                              | 1/2   | 1033131 |
| 4.1.11   | Jared | major Service.<br>tighten yoke/tail shaft<br>adjust brake.                                           | 1     | 512881  |
| 13.1.11  | blue  | remove gearbox                                                                                       | 8     | 1033232 |
| 18.1.11  | Jared | tighten yoke & brake. ✓                                                                              | 5     | 1033281 |
| 27.1.11  | Jared | minor Service                                                                                        | 2     | 1033345 |
| 18.2.11  | Jared | Rebolt gearbox back in. ✓                                                                            | 5     | 1033425 |
| 7.4.11   | Jared | minor service replace rear u-bolts ✓                                                                 | 1 1/2 | 1033823 |

|         |       |                           |       | PM 61    |
|---------|-------|---------------------------|-------|----------|
| DATE    | NAME  | DESCRIPTION               | HOURS | KM'S     |
| 21.5.10 | hurie | general check over        |       |          |
|         |       | & greased truck ✓         | 2 1/2 | 1031885  |
| 4.6.10  | pete  | major Service             | 2 1/2 | 1031943  |
| 22.6.10 | pete  | minor Service. 1032010    | 2     | 383027   |
| 22.7.10 | blue  | travel to Nelson fit      |       |          |
|         |       | drive shaft ✓             | 3     | 1032038  |
| 30.6.10 | pete  | Major Service             |       | (389910) |
|         |       | fix lights/fix mudflaps   | 4     |          |
| 21.7.10 | blue  | Travel to Nelson remove   | ✓     | 1032415  |
|         |       | tailshaft ✓               | 3 1/2 | 1032416  |
| 21.7.10 | blue  | Travel to Nelson tow      |       |          |
|         |       | truck of road ✓           | 2     | 1032417  |
| 16.8.10 | Jared | replace exhaust flex/     |       |          |
|         |       | replace airline ✓         | 2     | 1032418  |
| 19.8.10 | Jared | replace air line/replace  |       |          |
|         |       | Valve on side of          |       |          |
|         |       | gearbox/ ✓                | 6 1/2 | 1032419  |
| 25.8.10 | Dean  | repair headlights ✓       | 1 1/2 | 1032420  |
| 26.8.10 | Dean  | work on lights ✓          | 2     | 1032421  |
| 28.8.10 | Dean  | take to Pat Duffy ✓       | 1/2   | 1032422  |
| 31.8.10 | Jared | major Service (429111) ✓  |       | 1032423  |
|         |       | replace headlight/replace | 3     |          |
|         |       | hose on hydraulic hose    |       |          |
| 9.9.10  | blue  | put computer on truck     |       |          |
|         |       | check for faults ✓        | 1     | 1032424  |
| 18.8.10 | pete  | get hose made and         |       |          |
|         |       | fit to truck ✓            | 1 1/2 | 1032650  |

|          |        |                                              | PM61   |            |
|----------|--------|----------------------------------------------|--------|------------|
| DATE     | NAME   | DESCRIPTION                                  | HOURS  | KM'S       |
| 19/11/09 | P Hill | 'MINOR' SERVICE 3 EXT TRIAL OIL SAMPLE TAKEN | 2      | 250,934    |
|          |        | Unit <u>PM 61</u>                            |        |            |
|          |        | Compartment <u>ENG</u>                       |        |            |
|          |        | Notes <u>19-11-09</u>                        |        |            |
|          |        | <u>P.C.</u>                                  |        |            |
|          |        | Unit <u>61</u>                               |        |            |
|          |        | Compartment                                  |        |            |
|          |        | Notes <u>255 314</u>                         |        |            |
| 25-11-09 |        | <u>25711-09</u>                              |        |            |
|          |        |                                              |        |            |
| 2/12/09  | P Hill | 'MAJOR' SERVICE oil sample taken             | 2      | 260,170    |
|          |        | Unit <u>61</u>                               |        |            |
|          |        | Compartment                                  |        |            |
|          |        | Notes <u>40000</u>                           |        |            |
|          |        | <u>2-12-10</u>                               |        |            |
| 12-1-10  | Dem    | minor service ✓ 1031762                      | 2710   | 1.5        |
| 28-1-10  | Blue   | minor service ✓ 1031763                      | 28339  | 1.5        |
|          |        |                                              |        |            |
| 24/2/10  | R Hill | 'MAJOR' SERVICE ✓ 1031767                    | 2      | 302,385    |
| 10/3/10  | R Hill | 'MINOR' SERVICE ✓ 1031276                    | 1 1/2  | 310,128    |
| 26/3/10  | R Hill | 'MINOR' SERVICE ✓ 1031299                    | 2      | 320,663    |
| 11-2-10  | Blue   | Service minor ✓ 1031764                      | 1.5    | 292,392    |
| 3-1-10   | Dem    | repair exhaust clean                         |        |            |
|          |        | radiator ✓                                   | 1h     | 1031765    |
| 12/4/10  | P Hill | 'MAJOR' SERVICE ✓ 1031766                    | 1 1/2  | 331,345    |
| 22-4-10  | pete   | minor service ✓ 1031767                      | 3 1/2h | 342,063    |
| 28-4-10  | pete   | test intercooler hose ✓                      | 1 1/2  | 1031768    |
| 7-5-10   | Dem    | fan R/S ✓                                    | 3      | 1031769    |
| 8-5-10   | Blue   | minor service ✓ 1031770                      | 1 1/2  | 353,006 km |
| 21-5-10  | blue   | minor service 1031884 ✓                      | 1      | 360,504    |

Pm 61

| DATE     | NAME       | DESCRIPTION                                                                          | HOURS | KM'S      |
|----------|------------|--------------------------------------------------------------------------------------|-------|-----------|
| 9/4/09   | P.Hill     | "MINOR" SERVICE                                                                      | 1 1/2 | 111,762   |
| 11/5/09  | P.Hill     | "MINOR" SERVICE 2                                                                    | 2 1/2 | 120,243   |
|          |            | EXTENDED TRIAL OIL SAMPLE TAKEN                                                      |       |           |
| 13/5/09  | P.Hill     | OIL SAMPLE TAKEN                                                                     | 2 1/2 | 125,375   |
|          |            | 25000 FOR YOUR RECORDS<br>SAMPLE NUMBER<br>No: 34295                                 |       |           |
| 21/5/09  | P.Hill     | "MAJOR" SERVICE                                                                      | 1 1/2 | 130,345   |
|          |            | EXTENDED TRIAL                                                                       |       |           |
|          |            | 30,000km OIL SAMPLE TAKEN                                                            |       |           |
|          |            | FOR YOUR RECORDS<br>SAMPLE NUMBER<br>No: 34292                                       |       |           |
| 1/6/09   | Blue       | Take Truck to JIB Inter                                                              | 1/2   | 30094     |
| 5/6/09   | P.Hill     | "MINOR" SERVICE (30133)                                                              | 2     | 141,974   |
| 16/6/09  | Blue       | Remove kick panel Refitted collar on shaft                                           | 2.    | (30157)   |
| 19/6/09  | P.Hill     | "MINOR" SERVICE 2                                                                    | 3     | 152,215   |
|          |            | EXTENDED TRIAL                                                                       |       |           |
| 24/6/09  | P.Hill     | Oil sample taken                                                                     |       | 30201     |
|          |            | 20,000km oil sample TAKEN                                                            |       |           |
|          |            | FOR YOUR RECORDS<br>SAMPLE NUMBER<br>No: 39989                                       |       |           |
|          |            | 24/6                                                                                 |       |           |
|          |            | Oil sample taken                                                                     |       |           |
|          |            | 25,000km, Ext track                                                                  |       | 30252     |
|          |            | FOR YOUR RECORDS<br>SAMPLE NUMBER<br>No: 39988                                       |       |           |
|          |            | 24/6/1                                                                               |       |           |
| 3/7/09   | P.Hill     | "MAJOR" SERVICE                                                                      | 2 1/2 | 163,722   |
|          |            | EXT TRIAL OIL SAMPLE TAKEN                                                           |       |           |
|          |            | 30,000km                                                                             |       | 1030342   |
| 22/7/09  | G. Burkard | Remove & Repair ball bar + bolt                                                      | 3 1/2 | (1030462) |
|          |            | Ball bar back on / clean up                                                          |       |           |
| 22/7/09  | P.Hill     | "MINOR" SERVICE                                                                      | 1     | 171,343   |
| 3/8/09   | P.Hill     | "MINOR" SERVICE                                                                      | 2     | 180,565   |
| 17/8/09  | P.Hill     | "MAJOR" SERVICE                                                                      | 4 1/2 | 191,312   |
| 18/8/09  | P.Hill     | C-INSPECTION                                                                         | 4 1/2 | (1030590) |
| 26/9/09  | G Burkard  | "Minor Service"                                                                      | 1     | 216,083   |
| 26/9/09  | Blue       | help Buf                                                                             | 1     | 221,132   |
| 2/10/09  | P.Hill     | "MAJOR" SERVICE                                                                      | 2     | 230,741   |
| 16/10/09 | P.Hill     | "MINOR" SERVICE                                                                      | 2     | 240,422   |
| 11/9/09  | P.Hill     | MINOR SERVICE                                                                        | 1     | 1030906   |
| 6/11/09  | G Burkard  | Go to portland Air-up New Drive shaft/<br>Drive back to Depo / Repair battery<br>Box | 6     |           |

| DATE     | NAME    | DESCRIPTION                                                                                | HOURS | KM'S    |
|----------|---------|--------------------------------------------------------------------------------------------|-------|---------|
| 28/10/8  | BURF    | Modify Tread plate on chassis at back of cab                                               | 5     |         |
| 29/10/8  | BURF    | Finish tread plate / make bracket 4 hydraulic spool valve + air gauge + print              | 8     |         |
| 30/10/8  | BURF    | Shift hydraulics up to new bracket / Sort out air gauge / tie up hoses + cables.           | 3     |         |
| 31/10/8  | BURF    | hook up hydraulics to trailer / chade. What truck would turn without hooking up on trailer | 2     | 16465   |
| 1/11/8   | BURF    | MODIFY TREAD plate bracket                                                                 | 2     |         |
| 21/11/08 | P. Hill | "MINOR" SERVICE<br>Fit step to side in front of DRIVE right drive                          | 3 1/2 | 15,149  |
| 27/11/08 | P. Hill | "MAJOR" SERVICE<br>changed, Diff and G/box oils<br>OIL FILTER #XLF7111 - WATER #FS 1040    | 5     | 19,426  |
| 4/12/08  | P. Hill | <del>MAJOR</del> "MINOR" SERVICE                                                           | 2     | 24,332  |
| 31/12/08 | P. Hill | "MAJOR" SERVICE<br>Fit ESOC Fittings                                                       | 3     | 39,552  |
| 21/1/09  | Johnny  | A Service                                                                                  | 1 1/2 | 850330  |
| 7/2/09   | BURF    | MAJOR SERVICE<br>Replace Brake relay valve ABC 288251 on front diff.                       | 1     | 64,243  |
| 7/2/09   | Brett   | help with service                                                                          | 1     |         |
| 18/2/09  | Johnny  | G+C                                                                                        | 1     | 73626   |
| 18/2/09  | P. Hill | Help with service                                                                          | 1 1/2 |         |
| 27/2/9   | P. Hill | "MAJOR" SERVICE                                                                            | 1 1/2 | 80,353  |
| 13-3-9   | P. Hill | "MINOR" SERVICE                                                                            | 2     | 91,313  |
| 13-3-9   | JOHNSY  | " - - -"                                                                                   | 1 1/2 |         |
| 26/3/09  | P. Hill | "MAJOR" SERVICE<br>Sample taken<br>Exhaust fixed                                           | 3     | 101,036 |
| 30/3/09  | P. Hill | adjust clutch, change dump valve on rear diff                                              | 1 1/2 |         |

FOR YOUR RECORDS  
SAMPLE NUMBER  
No: 34300

Extended trial