

SERVICE TRAILER

Asset Details

Build Date:	
Make:	
Length:	
Sub Cat:	
Axle Config:	
Body Type:	SERVICE TRAILER
Model:	
ATM:	
Volume:	
Rating:	
Suspension:	
Axle Type:	
Rim Type:	
Tyre Size:	
Brakes:	
Coupling:	



Asset Identification

Rego:	TDG 633	State:		Expiry:		Papers:	NO
Plant No:		VIN / Chassis:	N/A				
S/N:		Hubometer:					

Features

FITTED WITH LUBE SYSTEM, PETROL COMPRESSOR

Condition

Location	Damage
OVERALL	POOR CONDITION
TYRES	FLAT