

## 2009 NISSAN NAVARA D22 ST-R 2.5 CR DUAL CAB UTILITY 4X4

### Asset Details

|                      |                       |
|----------------------|-----------------------|
| <b>Build Date:</b>   | 9/2009                |
| <b>Compliance:</b>   |                       |
| <b>Make:</b>         | NISSAN                |
| <b>Model:</b>        | NAVARA                |
| <b>Variant:</b>      | D22                   |
| <b>Series:</b>       | ST-R 2.5 CR           |
| <b>Body Type:</b>    | DUAL CAB UTILITY      |
| <b>Engine Size:</b>  | 4 CYLINDER, 3.0 LITRE |
| <b>Transmission:</b> | 5 SPEED MANUAL        |
| <b>Fuel Type:</b>    | DIESEL TURBO          |
| <b>Ext. Colour:</b>  | MAROON                |
| <b>Int. Colour:</b>  | BLACK/GREY            |
| <b>Doors:</b>        | 4                     |
| <b>Seats:</b>        | 5                     |
| <b>Drive Type:</b>   | 4X4                   |



### Asset Identification

|                   |                   |               |          |               |     |                       |            |
|-------------------|-------------------|---------------|----------|---------------|-----|-----------------------|------------|
| <b>Odometer:</b>  | 94,335kms         | <b>Rego:</b>  | S534 AEX | <b>State:</b> | SA  | <b>Expiry:</b>        | 17/09/2014 |
| <b>VIN:</b>       | MNTCPUD22A0002952 | <b>PIN:</b>   |          |               |     |                       |            |
| <b>Engine No:</b> | YD25166914T       | <b>Hours:</b> |          |               |     |                       |            |
| <b>Papers:</b>    | YES               | <b>Keys:</b>  | 1        | <b>Books:</b> | YES | <b>Service Books:</b> | YES        |

### Features

ABS, AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, SIDE STEP, (NO REMOTE LOCKING)  
HARD TOP UTE COVER  
REAR ROLL BAR, ALLOY  
DUAL BATTERIES  
SPARE TYRE

### Tyres

|                   |      |                   |      |                  |      |                  |      |               |  |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|--|
| <b>Front LHS:</b> | Good | <b>Front RHS:</b> | Good | <b>Rear LHS:</b> | Good | <b>Rear RHS:</b> | Good | <b>Spare:</b> |  |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|--|

### Condition

|                 |                                       |
|-----------------|---------------------------------------|
| <b>Location</b> | <b>Damage</b>                         |
| DUCO            | MINOR SCRATCHES & SCUFF MARKS OVERALL |