

## 2008 SUBARU FORRESTER S-3 XS STATION WAGON ALL

### Asset Details

|                      |               |
|----------------------|---------------|
| <b>Build Date:</b>   | 7/2008        |
| <b>Compliance:</b>   |               |
| <b>Make:</b>         | SUBARU        |
| <b>Model:</b>        | FORRESTER     |
| <b>Variant:</b>      | S-3 XS        |
| <b>Series:</b>       |               |
| <b>Body Type:</b>    | STATION WAGON |
| <b>Engine Size:</b>  | 4 CYLINDER    |
| <b>Transmission:</b> | AUTO          |
| <b>Fuel Type:</b>    | PETROL        |
| <b>Ext. Colour:</b>  | SILVER        |
| <b>Int. Colour:</b>  | BLACK         |
| <b>Doors:</b>        | 5             |
| <b>Seats:</b>        | 5             |
| <b>Drive Type:</b>   | ALL           |



### Asset Identification

|                   |                       |               |          |               |    |                       |    |
|-------------------|-----------------------|---------------|----------|---------------|----|-----------------------|----|
| <b>Odometer:</b>  | 111,556kms<br>SHOWING | <b>Rego:</b>  | S421 ANS | <b>State:</b> | SA | <b>Expiry:</b>        |    |
| <b>VIN:</b>       | JF2SH9KL59G011522     | <b>PIN:</b>   |          |               |    |                       |    |
| <b>Engine No:</b> | EJ25D535999           | <b>Hours:</b> |          |               |    |                       |    |
| <b>Papers:</b>    | NO                    | <b>Keys:</b>  | 1        | <b>Books:</b> | NO | <b>Service Books:</b> | NO |

### Features

ABS, AIR BAG, AIR CON, ALLOY WHEELS, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TRACTION CONTROL, POWER MIRRORS

### Tyres

|                   |      |                   |      |                  |      |                  |      |               |      |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|
| <b>Front LHS:</b> | Good | <b>Front RHS:</b> | Good | <b>Rear LHS:</b> | Good | <b>Rear RHS:</b> | Good | <b>Spare:</b> | Good |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|

### Condition

|                 |                 |
|-----------------|-----------------|
| <b>Location</b> | <b>Damage</b>   |
| DUCO            | MINOR SCRATCHES |