

RESTORATION PROJECT LEYLAND P76 SEDAN

Asset Details

Build Date:	
Compliance:	
Make:	LEYLAND
Model:	P76
Variant:	
Series:	
Body Type:	SEDAN
Engine Size:	V8
Transmission:	COLUMN SHIFT AUTO
Fuel Type:	PETROL
Ext. Colour:	BLACK
Int. Colour:	BLUE
Doors:	4
Seats:	5
Drive Type:	REAR



Asset Identification

Odometer:	62,260kms SHOWING	Rego:	NO PLATES	State:		Expiry:	
VIN:	UNACCESSABLE	PIN:					
Engine No:		Hours:					
Papers:	NO	Keys:	1	Books:	NO	Service Books:	NO

Features

TOW BAR

Condition

Location	Damage
DUCO	HEAVY RUST
BODY	INCOMPLETE
UPHOLSTERY	A/F