

1994 HOLDEN VR COMMODORE S SERIES 2 SEDAN

Asset Details

| | |
|----------------------|-----------------|
| Build Date: | 1994 |
| Compliance: | |
| Make: | HOLDEN |
| Model: | VR COMMODORE |
| Variant: | S |
| Series: | SERIES 2 |
| Body Type: | SEDAN |
| Engine Size: | 3.8 LTR V6 |
| Transmission: | 4 SPEED AUTO |
| Fuel Type: | PETROL |
| Ext. Colour: | BLUE |
| Int. Colour: | GREY CLOTH TRIM |
| Doors: | 4 |
| Seats: | 5 |
| Drive Type: | |



Asset Identification

| | | | | | | | |
|-------------------|-------------------|---------------|---------|---------------|----|-----------------------|------------|
| Odometer: | 208,616 | Rego: | XAF 563 | State: | SA | Expiry: | 04/04/2016 |
| VIN: | 6H8VRK19HSL753936 | PIN: | | | | | |
| Engine No: | HH1420964 | Hours: | | | | | |
| Papers: | NO | Keys: | 2 | Books: | NO | Service Books: | NO |

Features

AIR CON, ALLOY WHEELS, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, SPARE WHEEL, TOW BAR

Tyres

| | | | | | | | | | |
|-------------------|---------|-------------------|---------|------------------|---------|------------------|---------|---------------|---------|
| Front LHS: | Average | Front RHS: | Average | Rear LHS: | Average | Rear RHS: | Average | Spare: | Average |
|-------------------|---------|-------------------|---------|------------------|---------|------------------|---------|---------------|---------|

Condition

| Location | Damage |
|--------------|---------------------------------|
| BODY | OVERALL MINOR DENTS & SCRATCHES |
| TRANSMISSION | HAS ISSUES |