

## 2007 TOYOTA HILUX SR SERVICE UTILITY REAR WHEEL DRIVE

### Asset Details

<b>Build Date:</b>	1/2007
<b>Compliance:</b>	
<b>Make:</b>	TOYOTA
<b>Model:</b>	HILUX
<b>Variant:</b>	
<b>Series:</b>	SR
<b>Body Type:</b>	SERVICE UTILITY
<b>Engine Size:</b>	3 LITRE, D4 TURBO DIESEL
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	2
<b>Seats:</b>	3
<b>Drive Type:</b>	REAR WHEEL DRIVE



### Asset Identification

<b>Odometer:</b>	218,793kms INDICATED	<b>Rego:</b>	XMA 321	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	MROCZ12G900011843	<b>PIN:</b>					
<b>Engine No:</b>	1KD7252040	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	NO

### Features

ABS, AIR BAG, AIR CON, CD PLAYER, CENTRAL LOCKING, NUDGE BAR, POWER STEERING, POWER WINDOWS, SHELVEING, SPARE WHEEL, TOOL BOX, TOW BAR, TRADEMANS FITOUT, ALDOM SERVICE BODY, GAS-LIFT SIDE PANEL (PASSENGER SIDE), 2 x SLIDE DOORS (DRIVERS SIDE), REAR ENTRY CENTRAL LOCKER, SHELVEING, ANDERSON PLUG, UNDERTRAY TOOL BOX, WASH UP TANK, FRONT MOUNT CARRY BAR

KEY #36

### Tyres

<b>Front LHS:</b>	Poor	<b>Front RHS:</b>	Poor	<b>Rear LHS:</b>	Poor	<b>Rear RHS:</b>	Poor	<b>Spare:</b>	Poor
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------

### Condition

Location	Damage
BODY	MINOR SCRATCHES & DENTS
	REARVIEW MIRROR DETACHED
	FRONT LEFT BUMPER DAMAGE
	CRACK IN GRILL

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.