



# 2009 HYUNDAI iLOAD H-1 TQ-V VAN REAR WHEEL DRIVE

<b>Build Date:</b>	3/2009
<b>Compliance:</b>	5/2009
<b>Make:</b>	HYUNDAI
<b>Model:</b>	iLOAD
<b>Variant:</b>	H-1
<b>Series:</b>	TQ-V
<b>Body Type:</b>	VAN
<b>Engine Size:</b>	2.5 LITRE, 4 CYLINDER TURBO DIESEL
<b>Transmission:</b>	5 SPEED AUTOMATIC TRANSMISSION
<b>Fuel Type:</b>	
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	5
<b>Seats:</b>	3
<b>Drive Type:</b>	REAR WHEEL DRIVE



## Asset Identification

<b>Odometer:</b>	276,430kms INDICATED	<b>Rego:</b>	S868 ACJ	<b>State:</b>	SA	<b>Expiry:</b>	05/08/2018
<b>VIN:</b>	KMFWBH7JR9U147472			<b>PIN:</b>			
<b>Engine No:</b>	09C262230			<b>Hours:</b>			
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

## Features

AIR BAG, AIR CON, BLUETOOTH, CARGO BARRIER, CD PLAYER, CENTRAL LOCKING, POWER STEERING, POWER WINDOWS, ROOF RACKS, SHELVING, SPARE WHEEL, TOW BAR, TRADEMANS FITOUT, WEATHER STRIPS

KEY #14

## Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Average
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	---------

## Condition

Location	Damage
REAR RIGHT HAND	SCRAPE MARK
	MINOR PAINT CHIPS & SCRATCHES
DRIVER WEATHER	STRIP BROKEN