

1974 VOLVO 164 E SEDAN

Asset Details

| | |
|----------------------|------------|
| Build Date: | 2/1974 |
| Compliance: | |
| Make: | VOLVO |
| Model: | 164 |
| Variant: | E |
| Series: | |
| Body Type: | SEDAN |
| Engine Size: | 6 CYLINDER |
| Transmission: | AUTOMATIC |
| Fuel Type: | PETROL |
| Ext. Colour: | WHITE |
| Int. Colour: | LIGHT BLUE |
| Doors: | 4 |
| Seats: | 5 |
| Drive Type: | |



Asset Identification

| | | | | | | | |
|-------------------|----------------|---------------|---------|---------------|----|-----------------------|----|
| Odometer: | 249774 | Rego: | WJE 641 | State: | | Expiry: | |
| VIN: | 1644369A104381 | PIN: | | | | | |
| Engine No: | 751 | Hours: | | | | | |
| Papers: | NO | Keys: | 2 | Books: | NO | Service Books: | NO |

Features

AIR CON, SPARE WHEEL, TOW BAR

Tyres

| | | | | | | | | | |
|-------------------|---------|-------------------|------|------------------|---------|------------------|---------|---------------|---------|
| Front LHS: | Average | Front RHS: | Poor | Rear LHS: | Average | Rear RHS: | Average | Spare: | Average |
|-------------------|---------|-------------------|------|------------------|---------|------------------|---------|---------------|---------|

Condition

| Location | Damage |
|------------------------------|--|
| OVERALL | SURFACE RUST SPOTS |
| FRONT PASSENGER SIDE QUARTER | SLIGHT ACCIDENT DAMAGE AROUND HEADLIGHT TRIM |