

# 1979 HOLDEN HZ UTILITY 1 TONNER

## Asset Details

|                      |                           |
|----------------------|---------------------------|
| <b>Build Date:</b>   | 9/1979                    |
| <b>Compliance:</b>   |                           |
| <b>Make:</b>         | HOLDEN                    |
| <b>Model:</b>        | HZ                        |
| <b>Variant:</b>      |                           |
| <b>Series:</b>       |                           |
| <b>Body Type:</b>    | UTILITY 1 TONNER          |
| <b>Engine Size:</b>  | 253 V8                    |
| <b>Transmission:</b> | AUTOMATIC<br>TRANSMISSION |
| <b>Fuel Type:</b>    | GAS/PETROL                |
| <b>Ext. Colour:</b>  | WHITE DUCO                |
| <b>Int. Colour:</b>  | SADDLE VINYL              |
| <b>Doors:</b>        |                           |
| <b>Seats:</b>        |                           |
| <b>Drive Type:</b>   |                           |



## Asset Identification

|                   |                       |               |   |               |     |                       |    |
|-------------------|-----------------------|---------------|---|---------------|-----|-----------------------|----|
| <b>Odometer:</b>  | 278,609kms<br>SHOWING | <b>Rego:</b>  |   | <b>State:</b> |     | <b>Expiry:</b>        |    |
| <b>VIN:</b>       | CHZ67905A             | <b>PIN:</b>   |   |               |     |                       |    |
| <b>Engine No:</b> | VD13262               | <b>Hours:</b> |   |               |     |                       |    |
| <b>Papers:</b>    | NO                    | <b>Keys:</b>  | 1 | <b>Books:</b> | YES | <b>Service Books:</b> | NO |

## Features

TOOL BOX, TOW BAR, CAPRICE FRONT END FITTED

## Tyres

|                   |      |                   |      |                  |      |                  |      |               |      |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|
| <b>Front LHS:</b> | Poor | <b>Front RHS:</b> | Poor | <b>Rear LHS:</b> | Poor | <b>Rear RHS:</b> | Poor | <b>Spare:</b> | Poor |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|

## Condition

| Location | Damage                        |
|----------|-------------------------------|
| BODY     | RUST IN QUARTER PANELS, DOORS |