

## 2004 TOYOTA HIACE 100 LWB VAN

### Asset Details

<b>Build Date:</b>	2/2004
<b>Compliance:</b>	
<b>Make:</b>	TOYOTA
<b>Model:</b>	HIACE
<b>Variant:</b>	
<b>Series:</b>	100
<b>Body Type:</b>	LWB VAN
<b>Engine Size:</b>	3 LITRE, 4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	3
<b>Drive Type:</b>	RWD



### Asset Identification

<b>Odometer:</b>	291,748kms SHOWING	<b>Rego:</b>	WZU 678	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JT721LHH701037794	<b>PIN:</b>					
<b>Engine No:</b>	5L5431901	<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR CON, CARGO BARRIER, DECALS, LADDER RACK, POWER STEERING, ROOF RACKS, SHELVING, SPARE WHEEL, DRIVERS WEATHER STRIP, CARRY TUBE

KEY #35

### Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Poor
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	------

### Condition

Location	Damage
	ROOF LINER DETACHING
	DENT DRIVER DOOR
	TORN UPHOLSTERY
	SLIDE DOOR SEAL DETACHING & TORN
	SCRATCHES & PAINT CHIPS

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.