

## 2007 HYUNDAI iLOAD H-1 VAN

### Asset Details

<b>Build Date:</b>	2007
<b>Compliance:</b>	
<b>Make:</b>	HYUNDAI
<b>Model:</b>	iLOAD
<b>Variant:</b>	H-1
<b>Series:</b>	
<b>Body Type:</b>	VAN
<b>Engine Size:</b>	4 CYL
<b>Transmission:</b>	5 SPEED MANUAL
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	WHITE
<b>Int. Colour:</b>	GREY/CLOTH
<b>Doors:</b>	5
<b>Seats:</b>	3
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	147,384 KM	<b>Rego:</b>	XSS-751	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	KMFWBH7RR8UO44087	<b>PIN:</b>					
<b>Engine No:</b>	G4K67768792	<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>	2	<b>Books:</b>	NO	<b>Service Books:</b>	NO

### Features

AIR BAG, AIR CON, CARGO BARRIER, CD PLAYER, CENTRAL LOCKING, NUDGE BAR, POWER STEERING, POWER WINDOWS, SPARE WHEEL, FIAMA SIDE AWNING TIE DOWN POINTS IN REAR

### Condition

Location	Damage
NUDGE BAR	DENTED
BUMPER	DAMAGE PASSENGER SIDE, SCRAPES DRIVERS SIDE
PASSENGER SIDE SLIDING DOOR	IMPACT DAMAGE
DRIVER SIDE REAR DOOR	SCRAPES
DRIVER SIDE REAR	DENT & SCRAPES