

## 2001 MITSUBISHI MAGNA SOLARA SEDAN

### Asset Details

<b>Build Date:</b>	6/2001
<b>Compliance:</b>	
<b>Make:</b>	MITSUBISHI
<b>Model:</b>	MAGNA
<b>Variant:</b>	SOLARA
<b>Series:</b>	
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	6 CYLINDER
<b>Transmission:</b>	4 SPEED AUTOMATIC
<b>Fuel Type:</b>	UNLEADED
<b>Ext. Colour:</b>	WHITE
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	225279	<b>Rego:</b>	WXH640	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	6MMTJ8A421T020411	<b>PIN:</b>					
<b>Engine No:</b>	6G74M215758	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	NO	<b>Service Books:</b>	NO

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TOW BAR, KEY DOES NOT TURN IGNITION, REQUIRES CLEANING, PLEASE NOTE \*\*\*THE PLATES HAVE BEEN REMOVED AND THE VEHICLE WILL REQUIRE NEW PLATES\*\*\*

### Tyres

<b>Front LHS:</b>	Poor	<b>Front RHS:</b>	Poor	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Good
-------------------	------	-------------------	------	------------------	---------	------------------	---------	---------------	------

### Condition

Location	Damage
FRONT RIGHT BUMPER	DENT
DRIVERS SIDE	SCRAPED FROM FRONT TO BACK