

# 1985 HOLDEN COMMODORE SL BTI VK SEDAN

## Asset Details

<b>Build Date:</b>	11/1985
<b>Compliance:</b>	11/1985
<b>Make:</b>	HOLDEN
<b>Model:</b>	COMMODORE
<b>Variant:</b>	SL BTI
<b>Series:</b>	VK
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	5.0L
<b>Transmission:</b>	3 SPEED AUTOMATIC TRANSMISSION
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	BEIGE DUCO
<b>Int. Colour:</b>	BROWN
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	RWD



## Asset Identification

<b>Odometer:</b>	281,868kms SHOWING	<b>Rego:</b>	VTU 764	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	VK8VK19-BTI	<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>					
<b>Papers:</b>		<b>Keys:</b>	1	<b>Books:</b>		<b>Service Books:</b>	

## Features

AIR CON, POWER STEERING, SPARE WHEEL, TOW BAR, EX POLICE CAR  
LPG FITTED BUT NOT WORKING  
CAR RUNS, ALL FLUIDS RECENTLY CHANGED,  
NEW FRONT BRAKE HOSES FITTED  
NEW BATTERY FITTED

## Tyres

<b>Front LHS:</b>	Good	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	Average
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	---------

## Condition

Location	Damage
REAR WINDOW	SURFACE RUST
DRIVERS SEAT	TORN, WILL NEED RETRIM