



## 2016 VOLVO L120 WHEELED ARTICULATED FRONT END LOADER

#### **Asset Details**

2016 **Build Date:** 

Make: **VOLVO** 

Model: L120

Series:

**Drive Type:** 

**Axle Config:** 

WHEELED ARTICULATED **Body Type:** FRONT END LOADER

Gearbox:

**Transmission:** 

**VOLVO Engine Make:** 

**6 CYLINDER TURBO Engine Size:** 

DIESEL

**Fuel Type:** 

Diff Make / Size:

Suspension:

**Ext Colour:** 

Tyre Size:

**Tyre Condition:** 







Doors:	Seats:	Length:	Capacity:
Volume:	Height:	Width:	GVM:
GCM:	SWL:	HP:	Tare:

#### **Asset Identification**

Odometer:	Rego:	State:	Expiry:
VIN:		PIN:	VCEL120FT00027711
Engine No:		Hours:	9,751hours SHOWING
Papers:	Keys:	Books:	Service Books:

#### **Features**

179kw (217HP) ENCLOSED A/C CAB ROPS/FOPS GP BUCKET3.50m3 LED FORWARD & REAR SPOTLIGHTS & WARNING BEACONS REAR CCTV & LCD SCREEN MINE SPEC FIRE SUPPRESSION SYSTEM **BATTERY ISOLATION SWITCHES** QMW INDUSTRIES WORK PLATFORM CONTROL SYSTEM EMERGENCY PUSH BUTTON STOP SWITCHES REAR & SIDE MISSING 1 x DOOR GLASS

**KEY #58** ASSET #LS144





# 2016 VOLVO L120 WHEELED ARTICULATED FRONT END LOADER

### **Condition**

Location	Damage	
	MISSING 1 x DOOR GLASS	