

## 2011 TOYOTA HILUX WORKMATE KUN26R DUAL CAB UTE 4x4

### Asset Details

<b>Build Date:</b>	2011
<b>Compliance:</b>	2011
<b>Make:</b>	TOYOTA
<b>Model:</b>	HILUX
<b>Variant:</b>	WORKMATE
<b>Series:</b>	KUN26R
<b>Body Type:</b>	DUAL CAB UTE
<b>Engine Size:</b>	3.0 LITRE TURBO DIESEL
<b>Transmission:</b>	MANUAL TRANSMISSION
<b>Fuel Type:</b>	
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	4x4



### Asset Identification

<b>Odometer:</b>	213,115kms	<b>Rego:</b>	NO PLATES	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	MR0FZ22G901176689	<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>					
<b>Papers:</b>		<b>Keys:</b>	1	<b>Books:</b>		<b>Service Books:</b>	

### Features

ABS, AIR BAG, AIR CON, BULL BAR, DECALS, POWER STEERING, POWER WINDOWS, SIDE STEP, BATTERY ISOLATION SWITCH  
PLANT NO: LV191

KEY #41

### Condition

Location	Damage
TRANSMISSION/CLUTCH	PROBLEMS
REAR 1/4	DAMAGED/DENTS/SCRATCHES